

# Oil Field Environmental Incident Summary

**Incident:** 20130408114747      **Date/Time of Notice:** 04/08/2013 11:37

**Responsible Party:** Tony Lucero

**Well Operator:** ENERPLUS RESOURCES USA CORPORATION

**Well Name:** ATLAS 149-93-33C-28H

**Field Name:** MANDAREE

**Well File #:** 23227

**Date Incident:** 2/6/2013      **Time Incident:** 24:00

**Facility ID Number:**

**County:** DUNN

**Twp:** 149

**Rng:** 93

**Sec:** 33

**Qtr:** NE NW

**Location Description:** Release was confined to the well pad.

**Submitted By:** Tony Lucero

**Received By:**

**Contact Person:** Tony Lucero  
US BANK TOWER  
950 17TH ST STE 2200  
DENVER, CO 80202

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 3 Miles

**Distance Nearest Water Well:** 3 Miles

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0	barrels	0	barrels		
Brine	0	barrels	0	barrels		
Other	100	barrels	100	barrels	100	barrels

**Description of Other Released Contaminant:**

Frac cross-link gel

**Inspected:**

**Written Report Received:** 7/25/2016

**Clean Up Concluded:** 2/21/2013

**Risk Evaluation:**

None

**Areal Extent:**

Spill contained on well pad.

**Potential Environmental Impacts:**

None - Spill was contained on well pad.

**Action Taken or Planned:**

Had a vac truck on location. Was able to suck up 50 bbls of the cross link gel. The remaining gel started to freeze up and the frac crew shoveled it up into buckets and took to flowback tank.

**Wastes Disposal Location:** Approved landfill with other flowback debris.

**Agencies Involved:** MHA Energy and Environmental, BLM and BIA

**Updates**

---

**Date:** 4/8/2013      **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release appears to have happened during fracing operations, according to the report, and remained on the location. This is within MHA Nation boundaries, and was reported to MHA Energy, Environmental , BIA and BLM.